



Comprehensive Green Book

 www.checkmycar.ae

 Contact Us
+971 054 409 3009


 Mail Id
Checkmycar.ae@gmail.com

Inspection Details

Date	Time	Inspection Type	VIN Number
31-OCT-2026	3:01	600-Points	MA3NC2B11PA569214

Vehicle Summary

Suzuki Ertiga




Odometer Reading
63,699 Km

Fuel Type
Petrol


Make	Suzuki
Model	Ertiga
Model Year	2023
Regional Specs	GCC
Transmission	Automatic
Engine Size	4-cylinder
Odometer	Genuine
Spare Tyre	Available
Number of Keys	1
Vehicle Type	MPV
External Colour	White

Report Overview



Tyres

Spare tyre: Available



Rear Right (RR)

PASS

Manufacturing year
2025
Brand / Model
Westlake
Tyre size
195/55R16

Spare tyre (ST)

PASS

Availability
Available
Brand / Model
Westlake
Tyre size
195/55R16

Rear Left (RL)

PASS

Manufacturing year
2025
Brand / Model
Westlake
Tyre size
195/55R16

Front Right (FR)

PASS


Manufacturing year
2025
Brand / Model
Triangle ReliaX Touring TE307
Tyre size
195/55R16

Front Left (FL)

PASS

Manufacturing year
2025
Brand / Model
Westlake
Tyre size
195/55R16

Rim



Rear Right (RR)

PASS

Spare tyre (ST)

PASS

Rear Left (RL)

PASS


Front Right (FR)

PASS

Front Left (FL)

PASS

Brake



Rear Right (RR)

Brake Type
DRUM

SHOES PASS DRUM PASS

Rear Left (RL)

Brake Type
DRUM

SHOES PASS DRUM PASS

Front Right (FR)

Brake Type
DISC

PADS PASS DISC PASS

Front Left (FL)

Brake Type
DISC

PADS PASS DISC PASS

Suspension

Front Suspension

FAIL

Front left CV axle boot needs to be changed


Both front stabilizer bar bushes need to be changed



Rear Suspension

PASS

Interior & Exterior



1. Roof Lining

2. Rear View Mirror

3. Steering Wheel Upholstery

4. Seats Upholstery

5. Gear Lever

6. Trunk Lining

7. Armrest & Side Pockets

8. Dashboard

9. Floor Mats

10. Doors

11. Front Windscreen

12. Rear Windscreen

13. Side windows

14. Hood

15. Trunk

16. Front Bumper

17. Back Bumper

Interior & Exterior

Dashboard

Dashboard has scratches

Front Windscreen

Right lower cover missing

Front Bumper

Front bumper not aligned



Dashboard

Electrical

Gear Lever

PASS

Doors

PASS

Rear Windscreen

PASS

Steering

PASS

Key

PASS

Infotainment

PASS

Windows Operation

FAIL

Left rear door window adjust button not working

Seats Adjustment

PASS

Electrical

Door Lock

PASS

A/C Control & Cooling

FAIL

AC cooling weak



Center Console Buttons

PASS

Cameras

PASS

Gauges

PASS

Rear View / Side Mirror

PASS

A/C Grilles

PASS

Ignition System

PASS

Electrical

Brake Lights

PASS

Headlights

PASS

Fog Lights

PASS

Reverse Lights

PASS

Number Plate Lights

PASS

Indicators & Hazards

PASS

Wipers

PASS

Soft Closing Doors

N/A

Electrical

Sunroof / Moonroof

N/A

Interior Lights

PASS

Cruise Control

PASS


Horn

PASS

Parking Sensors

PASS

Body



Re-paint found

- Front Bumper: Re-Painted
Hood: Re-Painted
Front Left Fender: Re-Painted
Front Right Fender: Re-Painted
Front Left Door: Re-Painted
Front Right Door: Re-Painted
Roof: Re-Painted
- Rear Left Door: Re-Painted
Rear Right Door: Re-Painted
Rear Left Quarter: Re-Painted
Rear Right Quarter: Re-Painted
Trunk: Re-Painted
Rear Bumper: Re-Painted

Engine

Engine Upper Cover

PASS

Engine Shield Cover

PASS

Engine Mounts

PASS

Bonnet Hinge & Holder

FAIL

Bonnet open button detached

Turbo / Supercharger

N/A

Fender Liners

FAIL

Both front fender lower liners missing

Engine

Drive Belt / Pulleys

PASS

Engine Idle

PASS

Engine Oil Filler Cap

PASS

Radiator

PASS

Engine Oil Leaks

FAIL

Engine oil pan has accident damage and oil leakage



Engine

Engine Oil Condition

PASS

Coolant Condition

PASS

Coolant Cap

PASS

Hoses & Pipes

PASS

Exhaust System

PASS

4 Wheel Drive

N/A

Transmission

Transmission Fluid Level & Condition

PASS

Transmission Fluid Leaks

FAIL

Transmission joint has leakage



Gear Selector

PASS

Unusual Noise

PASS

Gear Shifting

PASS

Differential


PASS

Chassis & Subframe

REPAIRED

DAMAGED

CHECKED



1. Core support

2. Frame rail

3. Wheel house

4. Right fender apron

5. Shock tower/shock mount

6. Radiator side support (side baffle)

7. Left fender apron

8. Front body hinge pillar

9. Front floor board

10. Left door sill

11. Center pillar post (B pillar)

12. Mid floor board

13. Body quarter panel

14. C pillar

15. Seat frame

16. Rear floor panel

17. Left A pillar

18. Roof panel

19. Right door sill

20. Right A pillar

Inspector notes

Car has accident history


Front side repaired

Engine oil pan has accident damage

1. Core support: Front-end structure marked repaired

General Photos


Exterior



Interior



Engine Bay & Undercarriage




Inspector Comment

Comment

Car has accident history
All tyres manufactured in 2025; spare tyre available
Car fully repainted
Front side repaired
Front windshield right lower cover missing
Both front fender lower liners missing
Front bumper not aligned
Left rear door window adjust button not working
Bonnet open button detached
Dashboard has scratches
Front left CV axle boot needs to be changed
Both front stabilizer bar bushes need to be changed
AC cooling weak
Engine oil pan has accident damage and oil leakage
Transmission joint has leakage

Photos and Files



Vehicle compliance plate



Scanner VIN check

Disclaimer and Liability Policy

Inspection Accuracy Disclaimer

1. No Guarantee of Vehicle Condition

CheckMyCar conducts visual, non-invasive vehicle inspections at the time of assessment. The resulting report reflects the Inspector's professional observations to the best of their ability. However, it does not constitute a comprehensive or conclusive evaluation of the vehicle's overall condition. CheckMyCar disclaims all liability for any discrepancies, interpretations, or omissions related to vehicle conditions not identified during the inspection.

2. Seller Acknowledgment of Inspection Scope

By consenting to the inspection, the Seller acknowledges that the report is based solely on the Inspector's professional judgment and may differ from other assessments. CheckMyCar bears no responsibility for any disputes related to pre-existing defects or undeclared conditions not disclosed by the Seller.

Limitation of Liability to Sellers

3. No Contractual Liability to Seller

CheckMyCar's contractual obligation is solely to the Buyer. The inspection service is rendered for the Buyer's benefit, and CheckMyCar shall not be held liable to the Seller under any circumstances. Any disagreement regarding the report's findings must be resolved directly between the Buyer and Seller.

Seller Consent and Agreement

4. Acceptance of Independent Inspection Report

By permitting the inspection, the Seller agrees not to hold CheckMyCar liable for any disputes, claims, or discrepancies that may arise from the contents of the inspection report. The Seller understands that the report is an independent evaluation and does not affirm or validate the Seller's own representations about the vehicle.

Dispute Resolution

5. Resolution Process for Inspection-Related Disputes

In the event of a dispute by the Seller concerning the inspection findings and any resulting claims, all parties (Buyer, Seller, and CheckMyCar) agree to first engage in good-faith negotiations. Should the matter remain unresolved, it shall be subject to mediation or binding arbitration under the rules of the Dubai International Arbitration Centre (DIAC). CheckMyCar's liability, if any, shall be strictly limited as outlined in Section 10.

Disclaimer and Liability Policy

Indemnification

6. Seller's Obligation to Indemnify

The Seller agrees to indemnify, defend, and hold CheckMyCar harmless against any losses, claims, or disputes arising from inaccurate, misleading, or omitted information in the Seller's description of the vehicle prior to the inspection.

Thank You for Choosing CheckMyCar

 www.checkmycar.ae

